



	$L$	$D_1$	$D_2$ [mm]
KDR 03	3	3,6	7,0
KDR 04	4	3,6	7,0
KDR 05	5	3,6	7,0
KDR 06	6	3,6	7,0
KDR 07	7	3,6	7,0
KDR 08	8	3,6	7,0
KDR 09	9	3,6	7,0
KDR 10	10	3,6	7,0
KDR 15	15	3,6	7,0
KDR 20	20	3,6	7,0